

Voluntary Safety Recall Involving Incorrect Wiring Harness

Ford is conducting a voluntary safety recall involving an incorrect wiring harness service part that does not have the fusing protection intended for certain vehicle configurations or was mis-applied in 225,000 vehicles.

The service action involves the installation of a new wiring harness on cars. If the harnesses are not available, an electrical component will be replaced until a wiring harness is available.

These are quick repairs and will be done at no charge to customers. Owners of the affected vehicles will be notified by mail.

AFFECTED VEHICLES

The Wiring Harness (4W1Z-14A411-BC) was installed on approximately 225,000 vehicles of the noncompatible models and years listed below.

1992-2003 Econoline*	1993-1995 Taurus SHO
1992-1998 Crown Victoria/Grand Marquis	1992-1995 Town Car
1993 Bronco	1993 F-Series *
1995-1997 F-Series Stripped Chassis*	

* Gas engines only